



VTrak[®] E5000/EFA5310 Series

E5000/EFA5310 SR3.1 Release Notes
FW 11.06.0000.00

1. Release Summary

VTrak firmware version 11.06.0000.00 is a service release update to the FCS, PR1, SR1, SR2 and SR3 releases. It is designed for Windows, Mac and Linux environments.

Image version for SR3.1 release:

- Firmware: 11.06.0000.00

In addition to the fixes listed below, this release includes:

- Bug fixes.

The Firmware 11.06.0000.00 release contains the following fixes:

Ref #	Description
243760 247213	Fixed Ctrl unexpected crash during partner Ctrl fail-over and I/O failure was found.
246629	Fixed crashes during FC driver processing FC login or ELS pass through commands
243759	Fixed FC Ports of Ctrl or switch going offline, least seen after controller or port fail over/back, least with Cisco switch,
246741	Fixed FC Port base LUN mapping incorrect problem
247215	Fixed unexpected "Error (0x498f5402): SEP returned an error" while execute Factory defaults for enclosure, when JBOD(s) attached
246458	Fixed buzzer goes off when transported array is removed.
242920	Display BIOS updating progress in both GUI and CLI
247149 247233	Fixed SW (GUI/CLI) minor issues.

This document is applicable to the following PROMISE VTrak E5000 series models:

Model	Description
E5800fD	4U/24 FC, Dual controller
E5800fS	4U/24 FC, Single controller
E5600fD	3U/16 FC, Dual controller
E5600fS	3U/16 FC, Single controller
E5300fD	2U/12 FC, Dual controller
E5300fS	2U/12 FC, Single controller
E5320fD	2U/24 FC, Dual controller, 2.5" Drive Bays
E5320fS	2U/24 FC, Single controller, 2.5" Drive Bays

This Release supports the E5000 as a Node in a Promise A-Class Network File System High Availability Cluster. Any of the following A-Class Enclosures and the G1100 NAS Gateway can be used. A-Class Firmware 1.16.0000.00 or later required for full support.

Model	Description
A3800fDM	4U/24 FC, Dual controller
A3800fSL	4U/24 FC, Single controller
A3600fDM	3U/16 FC, Dual controller
G1100	NAS Gateway

The supported Expansion subsystems include:

Vendor	Platform	Description
Promise	VTrak J5320s	2U/24-bay JBOD, 12Gbs SAS to 12Gbs SAS (or 6Gbs SAS/SATA), 2.5" Drive Bays
	VTrak J5300s	2U/12 JBOD, 12Gbs SAS to 12Gbs SAS (or 6Gbs SAS/SATA)
	VTrak J5600s	3U/16 JBOD, 12Gbs SAS to 12Gbs SAS (or 6Gbs SAS/SATA)
	VTrak J5800s	4U/24 JBOD, 12Gbs SAS to 12Gbs SAS (or 6Gbs SAS/SATA)

Vendor	Platform	Description
Promise	VTrak J630s	3U/16-bay JBOD, 6Gbs SAS to 6Gbs SAS/SATA
	VTrak J830s	4U/24-bay JBOD, 6Gbs SAS to 6Gbs SAS/SATA
	VTrak J930s	4U/60-bay JBOD, 6Gbs SAS to 6Gbs SAS

2. Errata and known issues

Ref #	Description	Workaround/Solution
247570	Multipath I/O (MPIO) application in Windows Server 2016	<p>If Customer would utilize E5000 ALUA with multipath I/O in Windows Server 2016, customer could use native Microsoft Multipath I/O (MPIO) in Windows Server 2016</p> <p>Please follow listed procedure below to manually add the "Promise Vtrak" model to Microsoft MPIO DSM</p> <ol style="list-style-type: none"> 1. Please search and execute MPIO tool via Server Manager 2. Please follow steps in MPIO tool <ul style="list-style-type: none"> MPIO ----> Under MPIO Devices ---> Click add button -- --> Add the Model "Promise VTrak" 3. Then reboot the Client for the change to be effected.
247176	I/O request timed out may occur when E5000 process of BGA with heavy Windows I/O, and Windows Disk timed out value is 10 seconds. Attached ATTO Celerity FC162E (16G) or other kind FC HBA.	<p>If Customer wants to install/upgrade ATTO Celerity HBA, then manually customer needs to change the Windows disk timeout value (from Registry) to 60 seconds to avoid IO failure.</p> <p>Please execute regedit command, then search TimeoutValue and then enter 60 for following registry item</p> <p>HKEY_LOCAL_MACHINE --- >SYSTEM--->CurrentControlSet--- >Services-->Disk ---- >TimeoutValue 0X000000000a(10) change to 0X000000003c(60)</p>
242732	Alive Controller sometimes restart suddenly after user insert partner Controller into enclosure	<p>The issue could be resolved by Power CPLD v19.</p> <p>To prevent this problem while user</p>

Ref #	Description	Workaround/Solution
		hot plug (or insert) Controller FRU, user could check/upgrade both Firmware and BIOS to released SR3 version before insert partner Controller into enclosure
220589	The E5000 FC port does not support 4G FC SFP's (but 4G negotiation speed can be set for supported SFP's)	User needs to use 8G or 16G SFP's only in the E5000. Speed negotiation can link at 4 Gbps if the initiator (Host or switch) requires it.
231836	IO failure and "Non Disruptive firmware update has failed" event can occur while Non Disruptive Image Update (NDIU) flashing the E5000 SR1 code back to older releases.	<p>A user can upgrade from previous releases (FCS or PR1) to the E5000 SR1 via NDIU, but can't downgrade by NDIU from SR1 to previous releases.</p> <p>User can downgrade the SR1 FW to previous releases by DIU, or stop any background IOs when downgrading the FW by NDIU.</p>
229102	Mac users with a 16Gb Sanlink2 with Mac driver versions 2.05 or before may face I/O failure when there is a configuration with a Switch and Sanlink2 and a Controller port fail-over. With high I/O, it is possible that one of the controllers could go into an inaccessible state.	The issue is fixed by Sanlink2 driver version 2.0.6 and E5000 SR1 FW.
	If both Emulex 16GB HBA LPe16002B-M6 HBA and any make/ model of CISCO switch are set to "Loop" topology, the users will face incompatibility issue such as unable to negotiate through loop topology.	The Topology should be set to P2P, N_port or Auto on the switch and the HBA.
229338	In E5000 GUI, when SSL/TLS is enabled, Users will not be able to send mail using port nos. 456 & 587.	SMTP server works only on port 465 with SSL/TLS enabled.
229619	In E5000 GUI, User may see an error message such as "Cannot connect to	Refresh the browser to connect it

Ref #	Description	Workaround/Solution
	webserver", if the browser is kept idle for longer time (> 20 mins)	again to E5000 GUI
228912	In E5000 GUI, users will not be able to see any JBOD related information under the "Dashboard->Storage overview" screen.	User can alternatively get the JBOD related details from "Administration->Subsystem information" screen.
233000	A new user cannot be created using the GUI in Internet Explorer.	Users need to be created using Firefox or Chrome browsers
226688	FPNG command fail on Fabric mode with CISCO MDS 9148S switch The FC ping command in CLI from any target port to any initiator port thru the CISCO MDS 9148S switch fails.	Cisco reports that the MDS 9148 series does not support the FPING, they have initiated a request to add that support in MDS9148 series. Do not send FC ping command when connected FC switch is CISCO MDS 9148S
	For SSDs: The mixing of SAS and SATA SSD drives in the same array is not supported	Don't configure Arrays with a mixture of SAS and SATA SSD's.
	Mixing Trim supporting SSDs and Non-TRIM supporting SSDs in the same array is not supported.	Don't configure Arrays with a mixture of SSD drives that support TRIM with drives that don't support Trim. A drive that does not support TRIM will be displayed as a regular HDD in the GUI.
227932	After removing a Spare drive and reinserting it, or inserting a new drive in any slot, the drive may not be seen or be marked as "not usable". Rebooting the Controller fixes this.	Users who wish to remove a spare should delete the spare and then remove it. If a newly inserted drive is not usable because this procedure wasn't followed, then rebooting the controller may fix this issue.

Ref #	Description	Workaround/Solution
221229	In MAC OS X, if LD0 is mapped to a NON ZERO LMM entry AND if the Capacity is expanded (migration), the new capacity is not reported in Mac OS x without a reboot of the OS X Host	Reboot the OS X host in such an instance following a Capacity Expansion.
231248	A Mac host can get hung/panic if a user tries to mass delete large number of files created on a Large configuration (more than 10 LDs) on a E5000 controller.	Reboot the OS X host is such an event occurs.

3. Contacting Technical Support

PROMISE Support Website at http://www.promise.com/support/support_eng.asp

PROMISE E-mail Support at <http://support.promise.com/>

PROMISE Disclaimer

Notice:

Although PROMISE Technology, Inc. has attempted to ensure the accuracy of the content of this document; it is possible that this document may contain technical inaccuracies, typographical, or other errors. PROMISE Technology assumes no liability for any errors in this publication, and for damages, whether direct, indirect, incidental, and consequential or otherwise, that may result from such error, including, but not limited to loss of data or profits.

PROMISE Technology provides this publication "as is" without warranty of any kind, either express or implied, including, but not limited to implied warranties of merchantability or fitness for a particular purpose. The published information in the manual is subject to change without notice. Promise Technology reserves the right to make changes in the product design, layout, and driver revisions without notification to its users. This version of this document supersedes all previous versions.

© 2017 PROMISE Technology, Inc. All Rights Reserved. PROMISE, the PROMISE logo, VTrak, SmartStor, SuperTrak, FastTrak, VessRAID, Vess, PerfectPATH, PerfectRAID, SATA150, ULTRA133 and GreenRAID are registered or pending trademarks of PROMISE Technology, Inc. in the U.S. and other countries. All other trademarks are the property of their respective owners. Information regarding products, services and offerings may be superseded by subsequent documents and are subject to change without notice.