SANLink2 8G, 16G FC

SR 2.8

Release Note

Release Note Document
Version 2.8
Date: Sep 29, 2016

Copyright © 2016, Promise Technology, Inc.
All rights reserved

Revision History

Revision	Date	Release Label	Release Version	Notes
1.0	8/29/2014	8G FC SR1.0	Mac Driver: 1.0.46 Mac Utility: 1.00.0000.13	(1) This is only for SANLink2-8G FC product
2.0	11/11/2014	8G FC SR2.0 10G Base-T SR1.0 10G SFP+ FCS	10GE Mac Driver: 1.4.8 Mac Utility: 1.00.0000.21	(1) This is for SANLink2-10GE product (2) SANLink2 Utility supports SANLink2 series products
2.2	04/28/2015	16G FC FCS 8G FC SR2.2	Mac Driver: 1.2.2 Mac Utility: 1.02.0000.03	(1) First release for SANLink2 16G FC (2) Support FC Tape
2.2	05/13/2015	10G Base-T SR2.2 10G SFP+ SR2.2	10GE Mac Driver: 1.6.0, 1.6.2 Mac Utility: 1.02.0000.03	Bug Fixing
2.22	11/05/2015	8G FC SR2.22 16G FC SR2.22 10G Base-T SR2.22 10G SFP+ SR2.22	10GE Windows Driver 20.3 (64-bit only) Mac Utility: 1.02.0000.06	(1) Support Windows 10 (2) Support Mac OS 10.11
2.4	12/29/2015	8G FC SR2.4 16G FC SR2.4	Mac Driver: 1.2.5	Bug Fixing
2.6	05/06/2016	8G FC SR2.6 16G FC SR2.6 10G Base-T SR2.6 10G SFP+ SR2.6	FC Mac Driver 1.2.9 10G Mac Driver 1.7.4 Mac Utility 1.02.0000.09	Bug Fixing
2.8	09/29/2016	8G FC SR2.8 16G FC SR2.8	FC Mac Driver 2.0.4 Mac Utility 1.04.0000.03	To fix bug of Mac Pro 6,1 on OS X 10.12

Table of Contents

1. Contents for This Release 4
2. Release Notes and Versions 4
   2.1 MAC Driver for SANLink2 FC series 4
      2.1.1 Current version (SR2.8) 4
      2.1.2 Previous released version (SR2.6) 4
      2.1.3 Change List 4
   2.2 MAC Driver for SANLink2 10G series 4
      2.2.1 Current version (SR2.8) 4
      2.2.2 Previous released version (SR2.6) 4
   2.3 64-bit Windows Driver for SANLink2 10G series 5
      2.3.1 Current version (SR2.8) 5
      2.3.2 Previous released version (SR2.22) 5
3. MAC Utility 5
   3.1 Current Version (SR2.8) 5
   3.2 Previous Released Version (SR2.6) 5
   3.3 Change List 5
   4. Known Issues 6
   4.1 Mac Utility 6

1. Contents for This Release

The Service Release 2.8 is to release FC Mac Driver and Utility, mainly for bugs fixing. Because the driver's name is changed in this Service Release, the utility will also need to be upgraded.

2. Release Notes and Versions

2.1 MAC Driver for SANLink2 FC series

Unified Driver Installer for OS X 10.8.5 and above, including OS X 10.12.

2.1.1 Current version (SR2.8)

2.0.4

2.1.2 Previous released version (SR2.6)

1.2.9

2.1.3 Change List

- RB-229117: IO compare error under Mac OS 10.12 (Mac Pro 6,1 only).
- RB-229499: Add Abort command to SANLink2 driver.
- RB-227495: Change SANLink driver name from "SANLink2-FC" to "SANLink-FC"

2.2 MAC Driver for SANLink2 10G series

2.2.1 Current version (SR2.8)

No change

2.2.2 Previous released version (SR2.6)

1.7.4

2.3 64-bit Windows Driver for SANLink2 10G series

2.3.1 Current version (SR2.8)

No Change

2.3.2 Previous released version (SR2.22)

20.3

3. MAC Utility

3.1 Current Version (SR2.8)

1.04.0000.03

3.2 Previous Released Version (SR2.6)

1.02.0000.09

3.3 Change List

- RT-24727: Support new name of SANLink FC driver
- RB-219673: Add a link to collect logs for engineer analysis.

4. Known Issues

4.1 Mac Utility

1. While Mac utility is launching, adding 4 or more SANLink2 devices as daisy-chained, utility will perform no response if user unplug any device.
    - Workaround: 'Quit' the utility and re-launch it again
2. While Mac utility is launched firstly and then plug in SANLink2 10G, utility will perform no response occasionally and the device is not workable also.
    - Workaround: Restart the host with the SANLink2 10G connected, and re-launch the utility again



2F, No. 30, Industry E. Rd. IX, Science-Based Industrial Park, Hsinchu 30075, Taiwan, R.O.C.
Tel: +886-3-5782-395 Fax: +886-3-5782-390 www.promise.com