Pegasus2 R2+
Service Release Note

Release Note Document

Version 1.0
Date: Mar 09, 2016

Copyright © 2016, Promise Technology, Inc.
All rights reserved

Revision History

Revision	Date	Release Label	Release Version	Notes
1.0	3/9/2016	SR1.0	FW 1.0.0000.14 Mac SW:3.20.0000.15 Windows Driver 1.0.0.6 Windows SW: 1.04.0000.21	Bug fixing

Table of Contents

1. CONTENTS FOR THIS RELEASE 4

2. RELEASE NOTES AND VERSIONS 4

2.1 FIRMWARE (FW) 4
2.1.1 Current Version 4
2.1.2 Previous Released Version 4
2.1.3 Change List 4
2.2 MAC UTILITY 4
2.2.1 Current Version 4
2.2.2 Previous Released Version 4
2.2.3 Change List 4
2.3 WINDOWS DRIVER 4
2.3.1 Current Version 4
2.3.2 Previous Released Version 4
2.3.3 Change List 5
2.4 WINDOWS UTILITY 5
2.4.1 Current Version 5
2.4.2 Previous Released Version 5
2.4.3 Change List 5

1. Contents for This Release

The Service Release 1.0 includes bug fixing for firmware, Windows Driver, Promise Utility and Pegasus Utility for Pegasus2 R2+.

2. Release Notes and Versions

2.1 Firmware (FW)

2.1.1 Current Version

Service Release 1.0 (SR1.0) 1.0.0000.14

2.1.2 Previous Released Version

1st Release (FCS) 1.0.0000.12

2.1.3 Change List

1. RB-219162, 218631: abnormal LED Status in RAID1 rebuilding.
2. RB-218392: The capacity of RAID1 volume is incorrect after formatted when RAID1 is critical and USB is connected.
3. RB-218366: The capacity of RAID1 volume is incorrect if changing RAID mode from VHDD to RAID1
4. RB-219341: Correct VHDD reason to “RAID1 disks mismatched” while insert two different dives coming from different RAID1

2.2 MAC Utility

2.2.1 Current Version

Service Release 1.0 (SR1.0): 3.20.0000.15

2.2.2 Previous Released Version

1st Release (FCS): 3.20.0000.11

2.2.3 Change List

1. RB-219252: File system for Card reader pod is limited to FAT32 (<= 32GB) or ExFAT (> 32GB)
2. RB-220083: Rebuilding progress bar could be viewed via GUI.
3. RB-219312: System Monitor doesn't work with Media Bay

2.3 Windows Driver

2.3.1 Current Version

Service Release 1.0 (SR1.0): 1.0.0.6

2.3.2 Previous Released Version

1st Release (FCS): 1.0.0.3

2.3.3 Change List

RB-224546: [EVT/Win]In the Uninstall a program,R2+ show two version driver

2.4 Windows Utility

2.4.1 Current Version

Service Release 1.0 (SR1.0): 1.04.0000.21

2.4.2 Previous Released Version

1st Release (FCS): 1.04.0000.19

2.4.3 Change List

1. RB-219252: File system for Card reader pod is limited to FAT32 (<= 32GB) or ExFAT (> 32GB)
2. RB-220083: Rebuilding progress bar could be viewed via GUI.
3. RB-219312: System Monitor doesn't work with Media Bay