SANLink2 10G BaseT
SANLink2 10G SFP+

SR 3.0.4

Release Note

Release Note Document
Version 3.0.4
Date: Sep 25, 2017

Copyright © 2017, Promise Technology, Inc.
All rights reserved

Revision History

Revision	Date	Release Label	Release Version	Notes
2.2	04/28/2015	16G FC FCS 8G FC SR2.2	Mac Driver: 1.2.2 Mac Utility: 1.02.0000.03	(1) First release for SANLink2 16G FC (2) Support FC Tape
2.2	05/13/2015	10G Base-T SR2.2 10G SFP+ SR2.2	10GE Mac Driver: 1.6.0, 1.6.2 Mac Utility: 1.02.0000.03	Bug Fixing
2.22	11/05/2015	8G FC SR2.22 16G FC SR2.22 10G Base-T SR2.22 10G SFP+ SR2.22	10GE Windows Driver 20.3 (64-bit only) Mac Utility: 1.02.0000.06	(1) Support Windows 10 (2) Support Mac OS 10.11
2.4	12/29/2015	8G FC SR2.4 16G FC SR2.4	Mac Driver: 1.2.5	Bug Fixing
2.6	05/06/2016	8G FC SR2.6 16G FC SR2.6 10G Base-T SR2.6 10G SFP+ SR2.6	FC Mac Driver 1.2.9 10G Mac Driver 1.7.4 Mac Utility 1.02.0000.09	Bug Fixing
2.8	09/29/2016	8G FC SR2.8 16G FC SR2.8	FC Mac Driver 2.0.4 Mac Utility 1.04.0000.03	To fix bug of Mac Pro 6,1 on OS X 10.12
3.0	12/20/2016	SANLink3 F2	FC Mac Driver 2.0.6 Mac Utility 1.04.0000.06	First Release for SANLink3 F2
3.0.2	04/18/2017	SANLink2 series SANLink3 F2	FC Mac Driver 2.0.7 10G Mac Driver 1.8.1 Mac Utility 1.04.0000.08	Bug Fixing
3.0.4	09/25/2017	SANLin2 10G series	10G Mac Driver 1.8.2	Bug fixing for macOS 10.13 beta

Table of Contents

1. Contents for This Release 4
2. Release Notes and Versions 4
    2.2 MAC Driver for SANLink2 10G series 4
        2.2.1 Current version (SR3.0.4) 4
        2.2.2 Previous released version (SR3.0.2) 4
        2.2.3 Change List 4
    2.3 64-bit Windows Driver for SANLink2 10G series 4
        2.3.1 Current version (SR3.0.4) 4
        2.3.2 Previous released version (SR2.22) 4
3. MAC Utility 5
    3.1 Current Version (SR3.0.4) 5
    3.2 Previous Released Version (SR3.0.2) 5
4. Known Issues 5
    4.1 Mac Utility 5

1. Contents for This Release

The Service Release 3.0.4 is to release SANLink2 10G Mac Driver for bug fixing on macOS 10.13beta.

2. Release Notes and Versions

2.2 MAC Driver for SANLink2 10G series

2.2.1 Current version (SR3.0.4)

1.8.2

2.2.2 Previous released version (SR3.0.2)

1.8.1

2.2.3 Change List

- RB-239220: Mac vtd-fault when SANLink2-10G connects to Ethernet in macOS10.13beta

2.3 64-bit Windows Driver for SANLink2 10G series

2.3.1 Current version (SR3.0.4)

No Change

2.3.2 Previous released version (SR2.22)

20.3

3. MAC Utility

3.1 Current Version (SR3.0.4)

No change

3.2 Previous Released Version (SR3.0.2)

1.04.0000.08

4. Known Issues

4.1 Mac Utility

1. While Mac utility is launching, adding 4 or more SANLink2 devices as daisy-chained, utility will perform no response if user unplug any device.
    - Workaround: 'Quit' the utility and re-launch it again
2. While Mac utility is launched firstly and then plug in SANLink2 10G, utility will perform no response occasionally and the device is not workable also.
    - Workaround: Restart the host with the SANLink2 10G connected, and re-launch the utility again



2F, No. 30, Industry E. Rd. IX, Science-Based Industrial Park, Hsinchu 30075, Taiwan, R.O.C.
Tel: +886-3-5782-395 Fax: +886-3-5782-390 www.promise.com