

# ***SANLink2 10GE***

## ***Base-T model & SFP+ model***

# **Windows Driver Release Note**

## **Release Note Document**

**Version 1.0**

**Date: Dec 5, 2014**

**Copyright © 2014, Promise Technology, Inc.  
All rights reserved**

**Revision History**

| <b>Revision</b> | <b>Date</b> | <b>Release Label</b> | <b>Release Version</b>          | <b>Notes</b>                                                    |
|-----------------|-------------|----------------------|---------------------------------|-----------------------------------------------------------------|
| 1.0             | 12/5/14     |                      | Intel Ethernet driver<br>3.9.58 | SANLink2 passed Intel®<br>Thunderbolt™ Certification<br>Program |
|                 |             |                      |                                 |                                                                 |

**Table of Contents**

**1. CONTENTS FOR THIS RELEASE..... 4**

**2. SANLINK2 10G BASE-T ..... 4**

    2.1 TESTED AND CERTIFIED ..... 4

**3. SANLINK2 10G SFP+ ..... 4**

    3.1 TESTED AND CERTIFIED BY INTEL ..... 4

**4. DOWNLOAD INTEL® ETHERNET DRIVER ..... 4**

**5. DISCLAIMER..... 4**

## 1. Contents for This Release

This Release Note is to inform certification and compliance of SANLink2 10GE products with Intel® Thunderbolt™ Certification process.

## 2. SANLink2 10G Base-T

### 2.1 Tested and Certified

|                |                                                                                                            |
|----------------|------------------------------------------------------------------------------------------------------------|
| Date Certified | 7/16/14                                                                                                    |
| Driver Version | Intel® Ethernet Controller X540-AT2 - 3.9.58.0                                                             |
| OS             | Windows 8.1 Enterprise Build 9200 , NT 6.2 – 64bit<br>Windows 7 Enterprise Build 7600 Service Pack 1 64bit |

#### Issues Observed While Testing

Unplug during file transfer may result device not being clean from Device Manager

This is driver related issue and will be fixed on the next driver version

## 3. SANLink2 10G SFP+

### 3.1 Tested and Certified by Intel

|                |                                                                                                            |
|----------------|------------------------------------------------------------------------------------------------------------|
| Date Certified | 10/17/14                                                                                                   |
| Driver Version | Intel® 82599ES 10 Gigabit Ethernet Controller -3.9.58.0                                                    |
| OS             | Windows 8.1 Enterprise Build 9200 , NT 6.2 – 64bit<br>Windows 7 Enterprise Build 7600 Service Pack 1 64bit |

#### Issues Observed While Testing

No Issues Observed While Testing

## 4. Download Intel® Ethernet driver

Intel drivers can be downloaded from Intel website

<https://downloadcenter.intel.com/SearchResult.aspx?lang=eng&keyword=x540-at2>

The latest driver version X540-AT2 and 82599 are in driver package v19.x as shown in the link.

## 5. Disclaimer

- This list is provided as a reference that the SANlink2 10G has passed the Intel® Thunderbolt Certification program using the referenced Intel Ethernet drivers.
- Promise supports SANLink2. Intel supports Intel® Ethernet driver.
- User will use Intel driver at their own discretion and will not hold Promise responsible to fix of any issue arises from using it. Please contact Intel support for any driver related issues that may be experienced.