



SANLink2 10G SFP+ Compatibility List

SANLink2 10G SFP+ Compatibility List

Compatibility List Versions Covered:

- **1.0:**
 - SANLink2 10G Driver (Mac) - Versions : 1.4.8 Date:10/06/2014
- **1.1:** Date:11/14/2014
 - Add Mac OS 10.10
 - Add 1 SFP+ Transceiver and 2 SFP+ cables
- **1.2:** Date:12/19/2014
 - SANLink2 10G Driver (Win) - Versions : 19.5
- **1.3:** Date:03/09/2015
 - Add Switches and cable
- **1.4:** Date:04/29/2015
 - Add OS and iMac
 - Update Mac Driver
- **1.5:** Date:07/24/2015
 - Add MacOS 10.10.4
- **1.6:** Date:10/05/2015
 - Add Windows 10
 - Update Windows Driver
- **V1.7:** Date:11/04/2015
 - Add MacOS 10.11.1
- **V1.8:** Date:02/17/2016
 - Add MacOS 10.11.3
- **V1.9:** Date:03/08/2016
 - Add 2 SFP+ Transceivers
- **V1.10:** Date:05/10/2016
 - Update Mac Driver
 - Add MacOS 10.11.4
 - Add HP Transceiver
- **V1.11:** Date:10/05/2016
 - Add MacOS 10.11.6 & MacOS10.12
 - Add Finisar Transceiver FTLX8574D3BCV
- **V1.12:** Date:10/05/2017
 - Update Mac Driver
 - Add MacOS 10.13
 - Add Apple adapter
- **V1.13:** Date:12/04/2018
 - Add MacOS 10.14
- **V1.14:** Date:11/28/2019
 - Add MacOS 10.15

SANLink2 10G SFP+ Compatibility List

Latest SANLink Versions Covered:

- **SANLink2 Driver (Mac OS 10.9/10.10 or later)** - Versions : 1.6.0 /1.7.4/1.8.2
- **SANLink2 Driver (Mac OS 10.8.5)** - Versions : 1.6.2 / 1.7.4
- **SANLink2 10G Driver (Win)** - Versions : 19.5 / 20.3

DEVICE COMPATIBILITY NOTE:

Basic compatibility between the 3rd party device and Promise device has been verified in typical configurations, unless otherwise stated.

DISCLAIMERS:

Only the versions available at time of testing have been verified, as listed. Corner cases may exist depending on user configuration etc. Individual 3rd party units may exhibit problems that did not show up in through the Promise test process. Published performance is not assured with configuration deviations.

Although Promise Technology has attempted to ensure the accuracy of the content of this document; it is possible that this document may contain technical inaccuracies, typographical, or other errors. Promise Technology assumes no liability for any , and for damages, whether direct, indirect, incidental, and consequential or otherwise, that may result from such error, including, but not limited to loss of data or profits.

Promise Technology provides this publication “as is” without warranty of any kind, either express or implied, including, but not limited to implied warranties of merchantability or fitness for a particular purpose. The published information in the manual is subject to change without notice. Promise Technology reserves the right to make changes in the product design, layout, and driver revisions without notification to its users. This version of this document supersedes all previous versions.

SANLink Device

Family	Description
Promise SANLink2	Dual- Port Thunderbolt2 to Dual-port 10G SFP+

Thunderbolt Supporting Systems

Vendor	Hardware	Identifier
Apple	Mac Book Pro	MacBookPro 8.2
		MacBookPro 10.1
		MacBookPro 11.1
		MacBookPro 13.1
		MacBookPro 13.2
		MacBookPro 13.3
	Mac Book Air	MacBookAir 6.2
	Mac Pro	MACPro 6.1
	iMac	iMac15.1
Vendor	Hardware	SBIOS
MSI	MSI Z77A-GD80	E7757IMS V1.7
Gigabyte	Gigabyte Z87X-UD5 TH	F2
ASUS	ASUS Z87-DELUXE QUAD	2103
HP	HP Z420	J61 V03.69
HP	HP Z820	J63 V03.69

Operating Systems

Vendor	OS
Apple	MacOS 10.8.x
	MacOS 10.9.x
	MacOS 10.10.x
	MacOS 10.11.x
	MacOS 10.12.x
	MacOS 10.13.x
	MacOS 10.14.x
	MacOS 10.15.x
Microsoft	Windows 7 SP1 x64
	Windows 8.1 x64
	Windows 10 x64

Promise Hardware

Family	Model	Description	Firmware
Vess R2000	Vess R2600tiD	3U/16-bay 10G/1G NAS to SAS/SATA RAID System	1.02.0000.51
	Vess R2600xi	3U/16-bay 1G NAS to SAS/SATA RAID System	1.02.0000.51
Pegasus	R4	4-Bay 10Gb Thunderbolt Storage System	5.02.0000.98
	R6	6-Bay 10Gb Thunderbolt Storage System	5.02.0000.98
Pegasus 2	M4	4-Bay 20Gb Thunderbolt Storage System	5.04.00000.36
	R4	4-Bay 20Gb Thunderbolt Storage System	5.04.00000.36
	R6	6-Bay 20Gb Thunderbolt Storage System	5.04.00000.36
	R8	8-Bay 20Gb Thunderbolt Storage System	5.04.00000.36
Smartstor	NS4600	4-bay iSCSI to SATA NAS System	3.01.0000.15
	NS6700	6-Bay iSCSI to SATA NAS System	3.01.0000.15

Display

Vendor	Type
Apple	Apple Thunderbolt Display (27")

Ethernet Switches

Vendor	Model	Ports
D-Link	DXS-3350SR	48x1Gb
HP	JC102A	24x10Gb
HP	2920 2-port 10GbE SFP+ Module (J9731A)	2x10Gb
DELL	N4032F	24x10Gb
NETGEAR	XS708E	1x10Gb shared port

SFP+ Transceiver

Vendor	Model	Supported Transfer Rate
Finisar	FTLX8571D3BCV	10G/1G
	FTLX1471D3BCL	10G/1G
	FTLX8571D3BCL	10G/1G
	FTLX8574D3BCV	10G/1G
AVAGO	709DMZ	10G/1G
FCI	TRX10GDP0311A1	10G
HP	J9150A	10G

SFP+ Cable

Vendor	Model	Length	Supported Transfer Rate
SrarTech	SFP-H10GB-CU2M	2M	10G
Intel	XDACBL3M	3M	10G
HP	X242 SFP+ SFP+ 7 m Direct Attach Cable (J9285B)	7M	10G

Adapter

Vendor	Model
Apple	Thunderbolt 3 (USB-C) to Thunderbolt 2 Adapter

*Apple Thunderbolt 3 (USB-C) to Thunderbolt 2 Adapter is only compatible with Mac system.

♠ End of Report ♠